

Appendix A

Photos









848 Fifth Street Contractor Photos

Exterior Photos

849 Roof eaves rotten and high potential of mold and structural damage



616 Long term gutter and stucco failure, high chance of internal rot and mold



848 Fifth Street Contractor Photos

416 most wood windows beyond repair, fully decayed



503 most wood windows beyond repair, fully decayed



848 Fifth Street Contractor Photos

439 most wood windows beyond repair, fully decayed



926 poorly maintained roof edges, high chance of internal water damage



848 Fifth Street Contractor Photos

621 roof failure, high chance of structural damage



356 long term stucco failure, high chance of structural damage



848 Fifth Street Contractor Photos

608 long term gutter failure, high chance of structural damage



848 Fifth Street Contractor Photos

Interior Photos

037 active water damage evident in basement along with mold



049 water damage



848 Fifth Street Contractor Photos

209 Rodent infestation (rats)

