


## Attachment # 1 Current State, Risks, and Concerns of the MVH Street Lights (Photos)



Typical MVH Site 1 lamp standard




Typical MVH Site 2 lamp standard



Typical Base MVH





Inside hand hole view of the base top and heavy metal decay



Typical base style



Typical base access hatch with inside metal corrosion

