

## Attachment 2

February 12, 2024 Inspection Photos

**From:** Bal Varn <br/>
<br/>
bvarn@newwestcity.ca> This is Exhibit " G " referred to in the **Sent:** February 12, 2024 4:19 PM affidavit of Bal Varn To: Bal Varn <br/>
<br/>
bvarn@newwestcity.ca> sworn before me at New Westminster Subject: RE: 347 Pembina in the Province of British Columbia this \_\_\_ day of See below for notes added. A Commissioner for taking Affidavits Sincerely, within British Columbia **Bal Varn** (she/her) | Bylaw Officer/ Senior Property Use & Tenant Support Coordinator T 604.527.4603 E bvarn@newwestcity.ca Vacation Alert: I will be away Feb 19-23, 2024 with no access to email during this time. City of New Westminster | Integrated Services 511 Royal Avenue, New Westminster, BC V3L 1H9 www.newwestcity.ca This message including attachments, transmitted herein is confidential and may contain privileged information. It is intended solely for the person or entity to which it is addressed. Any review, retransmission, dissemination, taking of any action in reliance upon, or other use of this information by persons or entities other than the intended recipient is prohibited. If you received this in error, please notify the sender and delete or destroy all copies.

From: Bal Varn <br/>
<br/>
bvarn@newwestcity.ca> **Sent:** Monday, February 12, 2024 3:51 PM **To:** Bal Varn < <u>bvarn@newwestcitv.ca</u>>

Subject: 347 Pembina

Pic 1 – image of exterior at rear of property



Pic 2 – work conducted at rear of the property



Pic 3 – stairs at south entry for 4 units




Pic 4 – laundry room on second level



Pic 5 – laundry room, second level. Window has been covered at exterior



Pic 6 – second floor bathroom



Pic 7 – second level. Wall to the left is hollow and taped together to create a wall.




Pic 8 – second level kitchen – 2 fridges seen and there are another 2 behind these fridges.



Pic 9 – Second level bedroom.



Pic 10 – second level kitchen – electrical cords used to plug all 4 refrigerators



Pic 10 – second level kitchen – electrical socket mounted to bottom of cabinet




 $\label{eq:pic11-ground} \mbox{Pic 11-ground level kitchen. Image of electrical wires running along walls.}$ 



Pic 12 – ground level kitchen – 2 fridges in basement



Pic 13 – ground level unit has breaker system at north wall



Pic 14 – ground level unit – space heaters used for heat



Pic 15 – ground level rear entry to home. Gutter/rain spout kicking out heat



Pic 16 – ground level rear entry hallway. Electrical wiring taped along wall



Pic 17 – ground level rear hallway to two units. Wall is an exterior wall on the left



Pic 18 – ground level rear entry hallway, there is a power cord with misc lights plugged into it.



Pic 19 - ground level unit at rear. The ceiling is aluminum and there are exterior pipes running through the room



Pic 20 – ground level rear entry unit has vents running along the ceiling.



 $\label{eq:pic21-ground} \ \ \text{Pic}\ \ 21-\text{ground level rear entry unit bedroom has aluminum ceiling and heater mid-wall}$ 




Pic 22 – ground level rear entry bathroom has plug in ventilation fans




Pic 23 – ground level rear entry kitchen – blocking door to another unit that is located at the front of the house.



Pic 24 – ground level rear entry kitchen foundation is exposed and flooring uneven



Pic 25 - ground level rear entry bedroom has a small narrow door opening. The left wall is not drywalled.




Pic 26 – ground level rear entry unit bedroom



Pic 27 – second level north entry bachelor suite with kitchen and bathroom



Pic 28 – second level north entry bachelor unit kitchen



Pic 29 – second level north entry bachelor unit bathroom



Pic 30 – second level north entry unit has a dryer in the bathroom



Pic 31 – second floor north entry bathroom bachelor unit



Sincerely,

**Bal Varn (she/her)**| Bylaw Officer/Tenant Support Coordinator T 604.527.4603 E bvarn@newwestcity.ca

☐ City of New Westminster | Intergrated Services 511 Royal Avenue, New Westminster, BC V3L 1H9 www.newwestcity.ca