

## Attachment 7

May 15, 2024 Inspection Photos

## **Stephanie Jarvis**

From: Bal Varn <br/>
Sent: Bal Varn <br/>
Friday, May 17, 2024 1:44 PM

To: Bal Varn

**Subject:** RE: 347 Pembina

## See notes below. Interior inspection on May 15 at 1:30pm

From: Bal Varn <br/>
Sent: Friday, May 17, 2024 8:14 AM<br/>
To: Bal Varn <br/>
Varn@newwestcity.ca>

Subject: 347 Pembina

Photo 1 – Image of main floor. The wall has been removed and the room is converted to a dining room



Photo 2 – image of front room on main level. Was a room but now a living space



Photo 3 – main floor of home, the wall between the living room and play room has been removed.




Photo 5 – Image of laundry room on the main floor past the paly room area




Photo 6- image of laundry room on the main floor. The wall separating the play room and the laundry room is a temporary wall and the window is covered with plywood. Unit 4 is on the other side of the window.



Photo 7 – image of kitchen on the main floor. The fridges have been pushed up against the back wall, three of them.



Photo 8 – Photo of ground floor kitchen with entry from front of home



Photo 9 – once vacant room 1B at ground level of home. Occupied by male from main floor



Photo 10 – Image of ground level room 1D was vacant last inspection, now occupied



Photo 11 – Image of laundry facilities outside north side of home



Photo 12 – Image of ground level unit 3 (back of home) – storage room



Photo 13- ground level unit 3 (back of home) image of bedroom - occupied



Photo 13 – image of framed entry in to ground level kitchen in unit 3 (rear of home)



Photo 14 – image of kitchen for unit 3 ground level (rear of home)



Sincerely,

**Bal Varn (she/her)**| Bylaw Officer/Senior Property Use & Tenant Support Coordinator T <u>604.527.4603</u> E <u>bvarn@newwestcity.ca</u>

City of New Westminster | Intergrated Services 511 Royal Avenue, New Westminster, BC V3L 1H9 www.newwestcity.ca